

Civil Aviation Authority of Nepal Flight Safety Standards Department

4111075 4111042 4111119

Fax:977-1-4111198

Sinamangal, Kathmandu, Nepal

Ref. AW | 594 | 71 | 72

Date: 6th April 2015

Airworthiness Circular

To, The QA Manager Budhha Air Pv. Ltd. Kathmandu, Nepal

Dear Sir,

With reference to the flight control(Aileron) pulley assembly bearing damage found in your ATR 42 aircraft bearing the Registration Mark 9N-AIM (MSN: 388), it is required that all of your ATR 42 series aircraft be inspected for the same reason within 15 days and submit the report on the inspection within the stipulate timeframe.

Sincerely Yours

Er. Samrat Pradhan

Sr. Officer

Airworthiness Inspection Division Flight Safety Standards Department

CC:

Director Genral, CAAN - Sir, for your kind information
DDG(2), CAAN - Sir, for your kind information
Chief, FSSD, CAAN - Sir, for your kind information
Chief, AID, FSSD - Sir, for your kind information